



TREE PROTECTION

SITE CLEARANCE & DEMOLITION

SITE GATES

SITE GATES

SITE GATES

SITE GATES





TREE PROTECTION

SUBSTRUCTURE WORKS

AREA CONSTRUCTED LATER

CARPARK CONSTRUCTION

AREA CONSTRUCTED LATER

SITE GATES

SITE GATES

SITE GATES

SITE GATES



SLAB ON GROUND


TREE PROTECTION

NEW TREES

CARPARK OPERATIONAL

NEW TREES

SITE GATES



SLAB ON GROUND


TREE PROTECTION

STRUCTURAL STEEL INSTALL

NEW TREES

NEW TREES

SITE GATES



TREE PROTECTION

NEW TREES

ROOF SHEETING INSTALL

NEW TREES

STRUCTURAL STEEL INSTALL

SITE GATES





TREE PROTECTION

NEW TREES

ROOF SHEETING COMPLETE


NEW TREES

SITE GATES

JUBILEE PARK STADIUM REDEVELOPMENT

STAGE 2

[C.2]
14.12.2021



TREE PROTECTION


NEW TREES

ROOF REMOVED FOR CLARITY

NEW TREES

SLAB ON GROUND WORKS

SITE GATES



TREE PROTECTION


NEW TREES

ROOF REMOVED FOR CLARITY

NEW TREES

SLAB ON GROUND WORKS

SITE GATES



TREE PROTECTION

NEW TREES

ROOF REMOVED FOR CLARITY

NEW TREES

SLAB ON GROUND WORKS

SITE GATES



TREE PROTECTION

NEW TREES

INTERNAL FITOUT WORKS

NEW TREES

EXTERNAL WORKS

SITE GATES



TREE PROTECTION

EXISTING BUILDING DEMOLITION

NEW TREES

STAGE 3 SECOND WEARING COURSE TO EASTERN CARPARK

NEW TREES

BUILDING OPERATIONAL

NEW TREES

EXTERNAL WORKS COMPLETE

NEW TREES



JUBILEE PARK STADIUM REDEVELOPMENT

PROJECT COMPLETE

[C.2]
14.12.2021